## ISO 9000 Status

		ənt	Assurance		ıct Eng.	ld & Paint		nping			Assembly - Set-Up	90
		Management	Quality Ass	Materials	New Product	Frame Weld	Machine	Metal Stamping	Chrome	ŧ	embly -	Maintenance
	ISO 9001 Element	Mar	Qua	Mat	New	Frar	Мас	Met	Chr	Paint	Ass	Mai
4.1	Management Responsibility	U										
4.2	Quality System	Α	Α									
4.3	Contract Review											
4.4	Design Control											
4.5	Document & Data Control	X	Α	Α	X	Α	U	Α	U	Α	Α	Α
4.6	Purchasing											
4.7	Control of Customer Supplied Product											
4.8	Product Identification and Traceability		Α	Α	X	Α	X	X	U	Α	Α	
4.9	Process Control		Α		X	Α	U	U	U	Α	Α	Α
4.10	Inspection & Testing		Α		X	Α	U	X	U	Α	Α	
4.11	Control of I, M&TE		Α		X	Α	X	X	U	Α	Α	
4.12	Inspection & Test Status		Α			Α	X	X	U	Α		
4.13	Control of Nonconforming Product		Α			Α	U	U	U	Α		
4.14	Corrective & Preventive Action	S	Α									
4.15	Handling, Storage, Preservation & Delivery				X							
4.16	Quality Records	X	S	Α	X	Α	X	X	Ū	Α	Α	X
4.17	Internal Quality Audits	S	Α									
4.18	Training	S										
4.19	Servicing											
4.20	Statistical Techniques		Α		X							

X	Not Yet Determined as of this Report Print Date			
S	Known Deficiencies - No Known Resolution Plan			
В	Known Deficiencies - Resolution Behind Schedule			
U	Resolution Plan - Unknown Status			
Α	Resolution Plan On Schedule			
X	Area Appears Compliant (Not Verified thru Audit)			
С	Area Compliant (Verfied Through Audit)			

Printed On: 3/7/98 at 7:25 AM.

Disk File Name: ISO Plant Status